

Product-Change Notification

Products affected: ICSC15520620LHA61, ICSC18517620LHA61, ICSC22515620LHA61, ICSC30513620LHA61, ICSC35512620LHA61, ICSC55510620LHA61, ICSC74580520LHA61, ICSC10670520LHA61, ICSC12660520LHA61, ICSC20650520LHA61, ICSC30640520LHA61, ICSC43630520LHA61, ICSC90420621LHA61, ICSC13517621LHA61, ICSC18515621LHA61, ICSC20513621LHA61, ICSC36510621LHA61, ICSC77570521LHA61, ICSC13650521LHA61, ICSC22640521LHA61, ICSC36630521LHA61

Effective date: Starting from next production lot


Details: Change from Ink marking to laser printing

For the reason of continuous product improvement, we plan to change the type printing from ink marking to laser print marking on the above-mentioned Common Mode choke part numbers. The below photo is for reference only, it shows part number ICSC20650520LHA61.

Samples are available, please ask your sales manager.

Laser printing (new)

Ink marking (old)



Knitter-switch, 17 February 2021

Christian Schmid

Christian Schmid